

Innholdsfortegnelse

13 Stitching data in model 1

13 Stitching data in model

Stitching data in the model with layers that have the prefix «R» will be easy to find and drag this data to the stitching directory depending on the software. Stitching data must have the same quality as input data. Input data will normally be established on the basis of measured data. Stitching should therefore be based on the same fixed marking basis from which the measurement was made.

From:

<https://proing.banenor.no/wiki/> - **Prosjekteringsveileder**

Permanent link:

<https://proing.banenor.no/wiki/digitalplan-en/stitching-en>

Last update: **2022/01/18 08:20**